


DR1000 Case Corner Removal Tool

The *High Tech Special Tool*, for removing the corner pieces, can be made from a piece of a plastic water or soda bottle (your favorite brand). It can be cut out with scissors. After cutting it out, fold it long ways, from slit to slit; this will double the strength w/o w/o reducing flexibility. The fold keeps the pieces together.

Simply insert the tool longways into the bottom (or top, for the upper corners) until it stops, and slide the corner off.



This picture shows the bottom RIGHT corner, as seen from the back, with the corners and back removed.

This is the latch ⇒



Insert the tool from the bottom, to depress the latch.

In this view, we will be looking at the edge of the tool.