



iLiad Patch Notes

Version 2.7.1

Content

1	Overview Software patch v2.7.1	3
1.1	Content Browser	3
1.2	Security Fixes	4
1.3	PDF Viewer	4
1.4	Network settings	4
2	Download instructions for software patch v2.7.1	5
2.1	How to create an account:	5
2.2	How to download and install the latest software patch: ..	6

All Rights reserved.

Reproduction in whole or in parts is prohibited
Without a written consent of the copyright owner.

iRex Technologies BV © 2006

iLiad Patch Notes Version 2.7.1

These Software Patch Notes cover an overview of what's new and the Installation instructions for the software patch 2.7.1 for the iLiad.

1 Overview Software patch v2.7.1

This software patch v2.7.1 is part of an ongoing process to improve the overall performance to ensure an even better electronic reading experience for our customers. We recommend that all users install this patch.

1.1 *Content Browser*

- TXT files now show the correct icon.
- Toolbar icons are now anti-aliased
- The Up-key will now allow you to exit the rename screen
- Bug fixed where you could no longer open a renamed container.
- Bug fixed where not all illegal characters for the rename function were replaced.
- After a search the search string will remain available.
- Bug fixed where low battery warning was not displayed when starting up with a low battery
- Bug fixed where multi clicking in the content browser could crash the system

- Bug fixed where a double press on the confirm key in the iLiad settings could crash the content browser
- Bug fixed where a double press on the confirm key in CF card menu with no CF card inserted would open the iLiad settings

1.2 Security Fixes

- Security fix for Xserver leak
- Security fix for leak in Profiles

1.3 PDF Viewer

- Zoom function improved
- Pre-rendering of internal hyperlinks in PDF documents
- Deactivating the keyboard in the PDF viewer no longer leaves a gray image

1.4 Network settings

- Bug fixed where connection manager could crashed when editing a profile

2 Download and Installation instructions for software patch v2.7.1

In order to download this patch and any future software releases you will need to create a user account to connect to iDS.

Note: These download and installation instructions are only applicable for software version 2.7. If you are running an older software version please consult the previous release notes which can be found here:

<http://www.irextechnologies.com/downloads/docs>.

2.1 *How to create an account:*

- Go to <https://myirex.irexnet.com/createuser.php> and fill in your e-mail address.
- You will receive an automatic e-mail with a password in your e-mail inbox.
- Configure the *iLiad Settings* on your iLiad and insert your e-mail address and the password you received.
- You are now ready to connect to iDS.

If you have an account you can download the latest software release from the iDS (iRex Delivery Service).

Note: Make sure that your iLiad is fully charged or connected to the power plug before starting the download).

2.2 How to download and install the latest software patch:

- Connect to iDS by pressing the connect key of your iLiad for 2 seconds.
- After connecting to the server you will get a message: ***Downloading Software Patch v2.7.1*** and the progress of the download.
- When the download is complete wait until the screen of the iLiad turns white.
- After this the iLiad will automatically restart itself.
- When the iLiad has restarted, it will reconnect to the iDS to check for any further downloads.
- When there are no additional downloads you will return to the Download history screen, and the installation is complete.